



**CLEANING PROCEDURE FOR SQUEALING
SLIDEOUT ARMS AND GEARPACKS**

1. Extend the slideout arms to check for traces of blast material or other debris on the top and sides of the inner tubes.
2. Wipe away all debris with a clean rag or towel to allow for smooth travel of slide tubes.
3. Spray the drive gear and bushings with any "Power Lube" product to loosen up any caked on debris or granules and to lubricate the gear and bearings.
4. Cycle the slideout several times to ensure smooth and quiet travel. No need to cycle all the way out to clear any debris from the drive mechanism.