


--- FIELD WIRING
 ——— FACTORY WIRING

PASSED DIELECTRIC



● = 3-way Splice

■ = Blue male quick connect to flag splice

■ = Yellow male quick connect to flag splice

X = Disconnected wire

**EasyStart
364**