




ACHD Installation Guide

Tools Required:	Parts Supplied:
Cross point screw driver	 Heating element
5/16" nut driver	 (6) 5/16" head screws


Electrical Warning: *Prior* to installation, disconnect 115V AC or shut off A/C circuit breaker to prevent electrical shock. There may be a charge on the Capacitor until discharged.




1. With the AC on a flat surface, remove outer shroud.




2. Remove evaporator cover.




3. Remove (2) screws that hold evaporator to bulkhead.



4. Install mesh screen (reinstall screws from step 3 and add (2) additional screws in locations shown).



5. Install heating element using provided screws.



6. Connect the 3-pin connector to the control box, if installed.



7. Secure heater lead with wire holder, as shown.



8. Reinstall evaporator cover.



Reinstall shroud.